

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

5201 12TH STREET, SOUTH (LUSTRON HOUSE)
Arlington
Virginia

HABS VA-1414

The interior photographs were taken in early spring; the exterior on April 13, 2006.

INDEX TO BLACK AND WHITE PHOTOGRAPHS

James W. Rosenthal, photographer, 2006

VA-1414-1	Frederick Street (southeast) elevation
VA-1414-2	Frederick Street elevation, with scale
VA-1414-3	Perspective view looking from the corner of Frederick Street and Twelfth Street
VA-1414-4	Closer view looking from the corner of Frederick Street and Twelfth Street
VA-1414-5	Twelfth Street (front) elevation
VA-1414-6	Close view of the Twelfth Street elevation to show flagstone steps and pathway to the porch, looking northeast
VA-1414-7	Detail view of the decorative downspout and concrete catchbasin at the base
VA-1414-8	Detail view on porch looking to northwest to the corner with mailbox
VA-1414-9	Oblique view looking west along the southwest or Twelfth Street elevation to picture window with steel lintel; note also the ventilation for the eaves

5201 12TH STREET, SOUTH (LUSTRON HOUSE)

HABS VA-1414

INDEX TO PHOTOGRAPHS

VA-1414-10	View looking west toward the northeast elevation to show gable and trellis
VA-1414-11	Interior view, perspective view in the master bedroom, looking west; note the built-ins and closets
VA-1414-12	Interior view, bathroom, looking northwest
VA-1414-13	Interior view, kitchen looking west
VA-1414-14	Interior view, utility room detail